

Mount Gilead

Cultural Landscape Report

Prepared for:

Fairfax County Park Authority
Fairfax County, Virginia

Prepared by:

John Milner Associates, Inc.
Charlottesville, Virginia

April 2006

Public Release Version

Credits

Fairfax County Park Authority

Michael Rierson, Manager, Resource Stewardship Branch, CLR Project Manager

Charles Smith, Natural Resource Management and Protection

Katarina Spears, Ellanor C. Lawrence Park, Site Historian

Elizabeth Crowell, Ph.D., Cultural Resource Management and Protection Section Manager

Sherry Frear, Park Planning and Development Division

Historic Centreville Society

Debbie Robison, SWSG

John Milner Associates, Inc.

Liz Sargent, Historical Landscape Architect and Project Manager

Laura Knott, Project Landscape Architect

Adriane Fowler, Project Designer

Julie Basic, Project Designer

Jacky Taylor, Landscape Historian

Amy Wells, Graphic Designer

Jes Koepfler, Production Assistant

Table of Contents

Administrative Data

Project Summary	1-1
Location and Description of Property	1-3
Project Scope	1-3
Project Methodology	1-4
Summary of Findings	1-8
Recommendations for Further Study	1-10

Site Physical History

Introduction	2-1
Prehistory to 1720	2-2
Early European Settlement and Establishment of Newgate, 1720–1792	2-8
Founding of Centreville, a Crossroads Community, 1792–1861	2-13
The Civil War, 1861–1865	2-20
Reconstruction and the Aftermath of the Civil War, 1865–1917	2-25
The Beginnings of Modernity in Centreville, 1917–1937	2-30
The New Deal Era, World War II, and Subsequent Suburban Development, 1937–1969	2-33
Encroaching Suburbanization and the Need to Protect Historic Centreville, 1969–2005	2-35

Existing Conditions

Introduction	3-1
Environmental Context and Setting	3-2
Cultural Context and Setting	3-3
Mount Gilead Landscape Description by Characteristic	3-4
Inventory of Landscape Features by Characteristic	3-12
Resources Associated with the Centreville Historic Overlay District	3-14

Analysis and Evaluation

Introduction	4-1
National Register Level Evaluation of Significance	4-1
Comparative Analysis	4-7
Integrity Assessment	4-17

Treatment Plan

Introduction	5-1
Treatment Plan Organization	5-1
Park Authority Management Goals, Issues, and Concerns	5-2
Recommended Treatment Alternative	5-2
Treatment Concept for Mount Gilead	5-6
General Management and Design Guidelines for Treatment	5-7
Landscape Management Zones	5-12
Treatment Plan	5-13

Centreville Historic Overlay District Design Guidelines

Introduction	6-1
Summary of Historic Overlay District Character	6-2
Goals for the District	6-4
Identification of District Zones and Entry Points	6-4
Guidelines and Recommendations for the Historic Overlay District	6-6

Bibliography

General Sources	B-1
Government Documents	B-4
Primary Sources	B-6
Online Sources	B-7
Maps, Plans, Plats, and Images	B-8

Maps, Figures, Diagrams, and Photographs

Administrative Data

Figure 1-1. Context and Location Maps.

Site Physical History

- Figure 2-1. Map showing Fairfax County, ca. 1745-48.
- Figure 2-2. Survey of Willoughby Newton's Lands, 1743.
- Figure 2-3. Thomas Jefferson's map of 1787 showing Newgate.
- Figure 2-4. Newgate Tavern, rear elevation, 1909.
- Figure 2-5. Newgate Tavern, front elevation, 1924.
- Figure 2-6. Newgate Tavern, rear elevation, 1924.
- Figure 2-7. Plat of Centreville, ca. 1800.
- Figure 2-8. Detail, ca. 1800 plat of Centreville, indicating general location of Mount Gilead property.
- Figure 2-9. Ca. 1800 plat superimposed on a 1973 Fairfax County Parcel Identification map.
- Figure 2-10. Adams Tanyard insurance policy, 1805.
- Figure 2-11. Portion of Bishop Mead's map of 1807 showing Centreville.

- Figure 2-12. Mount Gilead insurance policy, 1805.
- Figure 2-13. Interpretation of the location of Ann Adams' garden fence, ca. 1821, superimposed over a ca. 1937 aerial photograph of Centreville.
- Figure 2-14. Detail, the McDowell map showing agricultural lands around Centreville, ca. 1862.
- Figure 2-15. Map showing topography around Centreville, ca. 1861.
- Figure 2-16. Map of Centreville and vicinity, 1879.
- Figure 2-17. Braddock Road, 1862.
- Figure 2-18. Braddock Road, Centreville, ca. 1904.
- Figure 2-19. Havener House, 1907.
- Figure 2-20. Four Chimney House, 1862.
- Figure 2-21. Four Chimney House, 1918.
- Figure 2-22. Royal Oaks House, with the Spindle House beyond, ca. 1937.
- Figure 2-23. Centreville Methodist Church, 1905.
- Figure 2-24. St. John's Episcopal Church, 1970.
- Figure 2-25. Robert Sneden drawing of the Civil War-era defenses around Bull Run, ca. 1861.
- Figure 2-26. Detail, Hotchkiss Map of the area around Centreville showing roads, streams, rail lines, and high ground, ca. 1861.
- Figure 2-27. Sneden drawing illustrating the detailed Civil War defensive system around Centreville.
- Figure 2-28. Another Sneden drawing of the Civil War defensive system around Centreville.
- Figure 2-29. Illustration of the defense of Centreville, ca. 1861.
- Figure 2-30. Illustration of Centreville with Bull Run in the distance, ca. 1861.
- Figure 2-31. Principal Fort at Centreville, ca. 1861.
- Figure 2-32. Photograph of the Mount Gilead House during the Civil War.
- Figure 2-33. Quaker gun, detail.
- Figure 2-34. Quaker guns.
- Figure 2-35. Camp of Union forces.
- Figure 2-36. Winter camp at Centreville, after the Confederate pull-out, near the present-day junction of Routes 28 and 29.
- Figure 2-37. Centreville Methodist Church, used as a temporary hospital, 1861.
- Figure 2-38. Jamesson cemetery gate.
- Figure 2-39. Mount Gilead, 1909.
- Figure 2-40. The Brentwood, a Sears kit house model chosen by the Spindle family for their home in Centreville.
- Figure 2-41. Robert Spindle and his Brentwood model Sears kit house.
- Figure 2-42. The Spindle House in 2003.
- Figure 2-43. 1984 plat showing the Spindle House property.
- Figure 2-44. 1933 plat showing part of the Mount Gilead property and adjacent Carroll B. Carter property, ca. 1933.
- Figure 2-45. Mount Gilead, 1934.
- Figure 2-46. Mount Gilead, 1970.
- Figure 2-47. Mount Gilead with side addition, ca. 1970s.
- Figure 2-48. Mount Gilead garden area, 1970s.

- Figure 2-49. 1937 aerial of Mount Gilead.
Figure 2-50. Unenhanced version of the 1937 aerial showing additional site context.
Figure 2-51. Plat of Carroll B. Carter property located adjacent to Mount Gilead, 1938.
Figure 2-52. Mount Gilead, front façade, ca. 1948.
Figure 2-53. Mount Gilead, front façade and entrance drive, ca. 1948.
Figure 2-54. Mount Gilead, pillars, gate, and fence along Mount Gilead Road, ca. 1948.
Figure 2-55. Mount Gilead, looking across the entrance drive to the front yard. Long view visible in background, ca. 1948.
Figure 2-56. Mount Gilead side yard and long view, ca. 1948.
Figure 2-57. Sally King in the Mount Gilead vegetable garden, ca. 1948.
Figure 2-58. Sally and John King in the vegetable garden, ca. 1948.
Figure 2-59. Plat showing division of Mount Gilead property adjacent to Havener property, 1952.
Figure 2-60. Boxwood and rose plantings with the pond beyond, ca. 1970s.
Figure 2-61. Ca. 1960s view of the front façade of the Mount Gilead house and garage.
Figure 2-62. View of an unidentified woman standing in front of the Mount Gilead House.
Figure 2-63. Map of area with ca. 1970s subdivisions overlain by 18th century patent holders.
Figure 2-64. 1953 aerial photograph of Mount Gilead and vicinity.
Figure 2-65. Site plan, ca. 2000, included with results of archaeological investigations of the former kitchen site.
Figure 2-66. Suggested locations of Confederate defences of Centreville as mapped by Reverend William Peterson of St. John's ca. 1970.

'Existing Conditions Documentation

- Figure 3-1. Mount Gilead Context and Location Maps.
Figure 3-2. Area Landform and Topography.
Figure 3-3. Area Hydrology.
Figure 3-4. Centreville Historic Overlay District and the Mount Gilead Property.
Figure 3-5. Landscape Features, Mount Gilead Property.
Figure 3-6. Photographic Station Points Map.
- Photo 1. Relatively level topography associated with the Mount Gilead House environs.
Photo 2. Thames Creek.
Photo 3. Civil War earthwork remnant.
Photo 4. Jamesson cemetery.
Photo 5. Partially-screened view to nearby residential development.
Photo 6. View of new single-family homes across Mount Gilead Road.
Photo 7. View from the Spindle House.
Photo 8. Southern magnolia-lined entrance drive.
Photo 9. Mulch trail leading through the woodland.
Photo 10. Southern magnolia allée.
Photo 11. Mature specimen plantings set within the lawn.
Photo 12. Mature boxwood shrubs near the house.

- Photo 13. Foundation plantings around the house.
- Photo 14. Small garden area behind the house.
- Photo 15. Vegetative character of the woodland.
- Photo 16. Invasive Japanese stilt grass.
- Photo 17. Mount Gilead House.
- Photo 18. Mount Gilead garage.
- Photo 19. Mount Gilead garage, undergoing stabilization.
- Photo 20. Rear view, garage stabilization.
- Photo 21. One of the two summerhouses behind the Mount Gilead House.
- Photo 22. The Spindle House.
- Photo 23. The Sedinger House, recently collapsed.
- Photo 24. One of the stone pillars at the entrance drive.
- Photo 25. Interpretive sign near the property entrance.
- Photo 26. The white-painted picket fence behind the house.
- Photo 27. A stone pillar located in the woods behind the Mount Gilead House.
- Photo 28. Remnants of a stone pillar near the Spindle House.
- Photo 29. Remnants of an unidentified concrete structure.
- Photo 30. An oval concrete pond near the house.
- Photo 31. Sections of the wrought iron fence that once enclosed the Jamesson cemetery.
- Photo 32. A headstone within the cemetery.
- Photo 33. Wood post-and-rail fencing along the northwestern property boundary.
- Photo 34. Chain-link fencing elsewhere along the property boundary.
- Photo 35. A gate providing access between the Spindle and Mount Gilead Houses.
- Photo 36. Remnants of a wooden fence near the Spindle House.
- Photo 37. Ornamental wire fencing near the Spindle House.

Comparative Analysis

- Figure 4-1. Mount Gilead Contributing Resources.
- Figure 4-2. Mount Gilead Missing Features.
- Figure 4-3. Comparative Photographic pair 1.
- Figure 4-4. Comparative Photographic Pair 2.
- Figure 4-5. Comparative Photographic Pair 3.

Treatment Plan

- Figure 5-1. Landscape Management Zones and Sub-Areas.
- Figure 5-2. Historic Sites within the Vicinity of Centreville with Related Interpretive Themes.
- Figure 5-3. Treatment Recommendations for Entry Area.
- Figure 5-4. Treatment Recommendations for Earthworks and Jamesson Cemetery Areas.
- Figure 5-5. Treatment Recommendations for Northeast Lawn Area.
- Figure 5-6. Treatment Recommendations for Garden Area.
- Figure 5-7. Treatment Recommendations for South Lawn Area.
- Figure 5-8. Treatment Recommendations for Spindle House Area.
- Figure 5-9. Treatment Recommendations for Woodland Area.

Figure 5-10. Treatment Recommendations for Adams Tanyard Area.

Figure 5-11. Treatment Recommendations for Road Trace Area.

Centreville Historic Overlay District Design Guidelines

Figure 6-1. Map of Design Guideline Zones.

Figure 6-2. Braddock Road, 1862.

Figure 6-3. Original Centreville grid overlaid on 1973 parcel map.

Figure 6-4. Centreville streetscape, ca. 1904.

Figure 6-5. Havener House, 1907.

Figure 6-6. High-density residential development on Mount Gilead Road.

Figure 6-7. Outlet of culverted portion of Thames Creek.

Figure 6-8. Conceptual sketch of pedestrian pathways through a property.

Figure 6-9. Conceptual sketch of small, well-defined, parking lots screened and shaded by trees.

Figure 6-10. Low and visually open picket fence.

Figure 6-11. Contemporary light fixture with historic reference.

Figure 6-12. Simple, contemporary signage.

Figure 6-13. Simple, contemporary site furnishing.

Figure 6-14. Pedestrian-oriented urban character.

Figure 6-15. Diagram of Centreville's layers of public and private space.

Figure 6-16. Large building designed with complex massing for human scale.

Figure 6-17. Entrance and parking on the side of a building along Braddock Road.

Figure 6-18. View toward sound wall from Braddock Road.

Figure 6-19. Stone piers used at entrance to Stanley Historic District.